

August 2017

ENERGY SAFETY WARNING

Non-compliant and unsafe TPS Cable has been supplied in New Zealand

The 2 core +PE cable sold in 1.5 mm² and 2.5 mm² is marked 'EESS 150102-0'.

If seen for sale, at worksites or installed, anywhere in the course of your work, please immediately call Energy Safety on 0800 030 040.

Such cable installed will have to be removed and replaced. Do not issue a CoC for any installation containing this cable.

